

014 What is the insert-height of the copper wire on your welder?



What is the insert-height of the copper wire?

X1	135 cm
X6	115 cm
X8	140 cm
CM16	165 cm
CM 17	135 cm
CM20	80 cm
CM21	150 cm